

# Care, Maintenance, and Troubleshooting of HPLC Columns

## Part 2



Indranath Chakraborty

09/03/13

# Major Areas of Column Problems - Dramatic Changes in 3 Key Areas:

**1. HPLC System Pressure**

**2. Chromatogram - Peak Shape**

**3. Chromatogram - Peak Retention/Selectivity**



## 2. Peak Shape Issues in HPLC

- Split peaks
  - Peak tailing
  - Broad peaks
  - Poor efficiency (low N)
  - Inconsistent response
- 
- Many peak shape issues are also combinations - i.e. broad and tailing or tailing with increased retention

# Split Peaks


**Can be caused by:**

- Column contamination
- Partially plugged frit
- Column void (gap in packing bed)
- Injection solvent effects


## Split Peaks Column Contamination

Column: StableBond SB-C8, 4.6 x 150 mm, 5  $\mu$ m      Mobile Phase: 60% 25 mM  $\text{Na}_2\text{HPO}_4$ , pH 3.0 : 40% MeOH      Flow Rate: 1.0 mL/min  
Temperature: 35°C      Detection: UV 254 nm      Sample: Filtered OTC Cold Medication: 1. Pseudoephedrine      2. APAP      3. Unknown      4. Chlorpheniramine


Injection 1



Injection 30



Injection 1  
After Column Wash  
with 100% ACN



- Column washing eliminates the peak splitting, which resulted from a contaminant on the column.

## Split Peaks

# Injection Solvent Effects


Column: StableBond SB-C8, 4.6 x 150 mm, 5  $\mu$ m

Mobile Phase: 82% H<sub>2</sub>O : 18% ACN

Injection Volume: 30  $\mu$ L

Sample: 1. Caffeine 2. Salicylamide

**A. Injection Solvent  
100% Acetonitrile**




**B. Injection Solvent  
Mobile Phase**



- Injecting in a solvent stronger than the mobile phase can cause peak shape problems, such as peak splitting or broadening.
- Note: earlier peaks (low k) most affected

# Peak Shape Problems - Doublets



- Void Volume in Column
- Partially Blocked Frit

## Determining the Cause of Split Peaks

- 1. Complex sample matrix or many samples analyzed - likely column contamination or partially plugged column frit.**
- 2. Mobile phase pH > 7 - likely column void due to silica dissolution (unless specialty column used, Zorbax Extend-C18 stable to pH 11)**
- 3. Injection solvent stronger than mobile phase - likely split *and* broad peaks, shape dependent on injection volume and k value.**




## Peak Tailing, Broadening and Loss of Efficiency (N, plates)

May be caused by:

1. Column “secondary interactions”
2. Column packing voids
3. Column contamination
4. Column aging
5. Column loading
6. Extra-column effects

## Peak Broadening, Splitting Column Void



- Multiple peak shape changes can be caused by the same column problem. In this case a void resulted from silica dissolved at high pH.

## Determining the Cause of Peak Tailing

- Evaluate mobile phase effects - alter mobile phase pH and additives to eliminate secondary interactions
- Evaluate column choice - try column with high purity silica or different bonding technology
- Reduce sample load – volume injection and concentration
- Eliminate extra-column effects – tubing, fittings, Uv cell
- Flush column and check for aging/void

## Reproducibility

Peak retention time precision:


⇒ with oven: \_\_\_\_\_ < 0.3%

⇒ without oven: \_\_\_\_\_ < 0.7%

Peak area precision: ≤ 1.5%

Typically,

- Area and Peak Height problems together point to the autosampler system
- Area and Retention Time problems together point to the pump



## Problems with Reproducibility – Peak Areas

Peak Areas not  
Reproducible

### With peak height


- Rotor seal cross-port leak or injection valve not tight
- Piston seal of metering unit leaking
- Needle partially blocked

### With retention time

- Variable pump flow rate

### Other

- Capillary from injector to detector not tight
- Detector equilibration problems



Thank you

Will be continued in next presentation.....